



ALERTA DE PEÇA SUSPEITA

SUSPECTED PART ALERT

UORG: SAR

APS n° 2023-01 (Revisão Original)

Data da revisão (issuance date): 05/06/2023

Assunto: Perda de certificação EASA ETSOA para produção Part 21 pela empresa Pronal S.A, fornecedora da Embraer.	Subject: <i>Loss of EASA ETSOA certification for Part 21 production by Pronal S.A, Embraer supplier.</i>
Background: Em novembro de 2021 a Embraer S.A recebeu uma carta (ver Anexo 1), do fornecedor Pronal S.A informando que sua autorização EASA ETSOA foi revogada. Essa revogação aconteceu em março de 2017 e os detalhes estão contidos no Anexo 2. O fornecedor também informou que, após auditoria da Autoridade de Aviação Civil Francesa, perdeu sua Aprovação de Produção Part 21. Nessa carta enviada pela Pronal, foram listados 37 itens fornecidos para a Embraer S.A após março de 2017 e que estão com o EASA Form 1 inválidos devido à revogação do ETSOA. .	Background: <i>In November 2021, Embraer S.A received a letter (see Annex 1), from the supplier Pronal S.A informing that its EASA ETSOA authorization was revoked. This revocation took place in March 2017 and the details are contained in Annex 2. The supplier also reported that, following an audit by the French Civil Aviation Authority, it lost its Part 21 Production Approval. In that letter sent by Pronal, 37 items supplied to Embraer S.A after March 2017 were listed and which are invalid EASA Form 1 due to the revocation of ETSOA.</i>
Status: () <i>Suspected Unapproved Part</i>	Status: (X) <i>Confirmed Unapproved Part</i>
Produto (Product): Legacy 600/650 (ERJ 135BJ)	
Nome da parte (Part name): RESERVOIR LEGACY 135 DROIT RESERVOIR LEGACY 135 GAUCHE	
Número da parte (Part Number): RAHE70370- RAHE70371-	
Números de série (Serial numbers): 428, 431, 432, 441, 442, 471, 472, 473, 474, 474, 475, 475, 476, 476, 477, 477, 478, 478, 479, 479, 480, 480, 481, 481, 482, 482, 483, 483, 484, 484, 485, 485, 486, 487, 488, 489, 490	