



ALERTA DE PEÇA SUSPEITA

SUSPECTED PART ALERT

UORG: SPO

APS nº 2023-02 (Revisão Original)

Data da revisão (*issuance date*): 07 NOV 2023

Assunto:

Notificação de parte aeronáutica extraviada - Nose Landing Gear Steering Plate Assembly

Subject:

Missing Aircraft Part Notification - Nose Landing Gear Steering Plate Assembly

Background:

Em 2019, ANAC foi notificada pela Gol Linhas Aéreas sobre o extravio de uma parte (Nose Landing Gear Steering Plate Assembly) que pode estar circulando na indústria aeronáutica sem a devida procedência e rastreabilidade.

Background:

In 2019, ANAC was notified by Gol Linhas Aéreas about the loss of a part (Nose Landing Gear Steering Plate Assembly) that may be circulating in the aeronautical industry without due origin and traceability.

Status: *Suspected Unapproved Part* *Confirmed Unapproved Part*

Produto (Product): 737-600, 737-700, 737-700C, 737-800, 737-900, 737-900ER, BBJ 737-700, BBJ 737-800

Nome da parte (Part name): Nose Landing Gear Steering Plate Assembly

Número da parte (Part Number): 162A1417-5

Números de série (Serial numbers): NMC2393