



Boletim Especial de Aeronavegabilidade (*Special Airworthiness Bulletin*)

ATA: 31 *Indicating/Recording Systems*

BEA Nº 2019-03

Subject: Suspected Unapproved Parts

Date: June 28th 2019

Introduction

This Special Airworthiness Bulletin (BEA) advises you, owners, operators and maintenance organizations, about suspected unapproved parts

Background

ANAC was informed by GOL Linhas Aéreas S.A. that the following part was lost on June 6th 2019, and it might have been used in the aviation industry without a due reliable origin and traceability:

Part Number (P/N)	Part Name	Serial Number (S/N)
DK 120	Underwater Locator Beacon	ST16168

Recommendation

Once it is a suspected unapproved part and, consequently, does not have an approval for return to service that certifies its airworthiness, ANAC recommends to the owners, operators and maintenance organizations the inspection of their aircraft regarding the installation of the Underwater Locator Beacon described above. If this part is installed, replace it with a new or used one before the next flight. The used parts shall have the records required by Regulamento Brasileiro de Aviação Civil (RBAC 43.9) for approval for return to service.

Note: The verification of the applicable maintenance records can be used instead of the inspection if it is possible to determine, following these records, that the part is not installed.

For information, contact

Agência Nacional de Aviação Civil (ANAC)
Gerência Geral de Certificação de Produto Aeronáutico (GGCP)
Rua Laurent Martins, 209, Jardim Esplanada II
12242-431 – São José dos Campos – SP.
Telefone: (12) 3203-6660
E-mail: pac@anac.gov.br