



# Boletim Especial de Aeronavegabilidade (*Special Airworthiness Bulletin*)

**ATA:** 32 *Landing Gear*  
34 *Navigation*

**BEA** Nº 2019-05

**Date:** September 17th 2019

**Subject:** Suspected Unapproved Parts

## Introduction

This Special Airworthiness Bulletin (BEA) advises you, owners, operators and maintenance organizations, about suspected unapproved parts

## Background

ANAC was recently informed by GOL Linhas Aéreas S.A. that the following parts were lost on April 14th 2018 (Part Numbers C20626200 and 2612312-1) and April 23th 2018 (Part Number 102LJ2AG), and they might have been used in the aviation industry without a due reliable origin and traceability:

Número de Parte (P/N)	Nomenclatura	Número de Série (S/N)
102LJ2AG	TAT Sensor	B49854
C20626200	Main Wheel Assy B800 Carbon Brake	7409C20626
2612312-1	Brake Assy B-800	B5513

## Recommendation

Once they are suspected unapproved parts and, consequently, do not have an approval for return to service that certifies their airworthiness, ANAC recommends to the owners, operators and maintenance organizations the inspection of their aircraft regarding the installation of the parts described above. If one of these parts is installed, replace it with a new or used one before the next flight. The used parts shall have the records required by Regulamento Brasileiro de Aviação Civil (RBAC 43.9) for approval for return to service.

Note: The verification of the applicable maintenance records can be used instead of the inspection if it is possible to determine, following these records, that the parts are not installed.

**For information, contact**

Agência Nacional de Aviação Civil (ANAC)  
Gerência Geral de Certificação de Produto Aeronáutico (GGCP)  
Rua Laurent Martins, 209, Jardim Esplanada II  
12242-431 – São José dos Campos – SP.  
Telefone: (12) 3203-6660  
E-mail: [pac@anac.gov.br](mailto:pac@anac.gov.br)